**RELEASE NOTES** 

# **Trimble Advanced Positioning**

+ + + + + + + + + +

# ALLOY AND NETR9 REFERENCE RECEIVERS

## Version 6.08 and 5.48 Firmware Release

These release notes describe the latest improvements made to the Trimble<sup>®</sup> Alloy<sup>™</sup> and NetR9<sup>®</sup> reference receivers.

- Introduction
- <u>Alloy version 6.08 features and changes</u>
- <u>Common features and changes</u>
- Feature comparison table
- Upgrade procedure
- Legal notices

## **Introduction**

These release notes describe improvements to the Alloy 6.08 firmware and NetR9 5.48 firmware. All Alloy receivers are entitled to firmware version 6.08. The NetR9 receiver must have a minimum firmware date of 1 November 2018 or later to use firmware version 5.48. If necessary, contact your Trimble distribution partner to purchase a NetR9 Trimble Protection Plan. Before you perform a firmware upgrade, ensure that you download and back up any files or configuration settings.

Version: 6.08 and 5.48 Date: August 2020



## Alloy version 6.08 features and changes

#### **Trimble ProPoint GNSS Engine**

Alloy receivers with the new Trimble ProPoint<sup>™</sup> GNSS engine (released in version 5.45) will have a new firmware numbering format. The numbering will change from 5.4X to 6.0X. The firmware changes will be used to differentiate between the new ProPoint GNSS engine and the previous GNSS engine. The Alloy active core version will still be 5.48, but the active version will be 6.08.



#### Tracking

#### IRNSS

• Adjusted the receiver's capacity to better detect IRNSS ephemeris information.

#### GLONASS

• Upgraded the Alloy receiver's tracking proficiency with GLONASS satellites in higher latitude regions.

#### BeiDou

- Updated the Alloy receiver's ability to handle BDS-III signals using TGD (Trimble GPS Raw Data) files.
- Improved the Alloy receiver's tracking capability with BeiDou GEO-stationary satellites.

## **Common features and changes**

These features and changes apply to both the Alloy and the NetR9 receiver.

#### Tracking

#### QZSS

• The receiver can support the QZSS satellite changes from MSAS(MTSAT-2) for SBAS.

#### SBAS

- Updated the L1 only position solution for SBAS and Autonomous solutions.
- Improved the SLAS (Sub-meter Level Augmentation Service) and MSAS performance (The Multi-functional Satellite Augmentation) to address transition issues with the satellite data.

#### BeiDou

• Addressed BINEX issues with incomplete BeiDou satellite C33 data by updating the ephemeris in the BINEX data format.

#### **Convert to RINEX**

• Corrected formatting issues with GLUT (GLONASS to UTC) in the receiver's RINEX ephemeris files.

#### Improvements

- Fixed issues with BeiDou sending incorrect RTCM data.
- The Alloy receiver's BINEX format will allow you to decide what Galileo ephemeris to use when sending BINEX data. You will have the choice to send legacy, upgraded, or both Galileo ephemeris. If you do not select an option, the receiver will only send the upgraded format.

I/O Configuration	าช			
TCP/IP 2273 V BINEX	· · ·			
Server: TCP Port: 2273	Delete			
Client				
Output only/Allow multiple con	nections			
Disable Nagle Algorithm				
UDP Mode				
Authenticate, set password:				
Measurements				
Off vInterval				
Smooth Pseudorange	Smooth Phase			
With Doppler	With Cycle Slip Counters			
With Clock Offsets - Always	Vith Clock Offsets - Always With Clock Offsets - On Rollovers			
Use record type 7F03 instead of	of 7F05			
MetaData				
off vinterval				
Marker Name	Marker Number	Station ID		
Receiver Type	Serial Number	Firmware Version		
Antenna Configuration	Antenna XYZ	Antenna Offset		
System Status Record	Met/Tilt Data	Galileo Ephemeris		
Off vinterval	Include in stream	0x01-0x14 (Upgraded) V		
OK Cancel		0x01-0x14 (Upgraded)		
		0x01-0x04		
		Both		

- Updated RTCM3 output to include MSM 3 for better performance of triple-frequency satellites.
- Enhanced the receiver's atmospheric modeling in autonomous and SBAS solutions.
- Adjusted the antenna configuration list to include new third-party antennas.
- Improved and brought back RTX positioning monitoring options in the web interface; the RTX option was not in firmware version 5.45.

## Position Monitoring@

Enable 🗆

Reference Long Reference H	leight: 0.000	' 0.00000 " [m]	●E○W		
Reference H		[m]			
	Here L				
		oad Current Pos	ition		
	Use Refe	rence Station Position	1		
	Force	reference station	position		
	Suspe	end CMR/RTCM	output if the monitor	ed position is out of to	lerance
Desition Trees	Lat Officiat Imi	Lan Officiat Incl	Linight Offent Incl.	Letil en Dennes [m]	Linkt Danman I
				Lat/Lon Ranges [m]	-
Autonomous	10.000	10.000	20.000	1 - 100	3 - 100
SBAS	5.000	5.000	10.000	0.3 - 100	1 - 100
			Construction of the second sec		1 - 100
VBS	1.000	1.000	3.000	0.15 - 100	0.5 - 100
VBS RTK	1.000 0.020	0.020	3.000	0.15 - 100 0.01 - 100	
					0.5 - 100
RTK	0.020	0.020	0.050	0.01 - 100	0.5 - 100 0.01 - 100
RTK DGNSS	0.020	0.020	0.050	0.01 - 100 0.15 - 100	0.5 - 100 0.01 - 100 0.5 - 100
RTK DGNSS HP	0.020	0.020	0.050 3.000 0.500	0.01 - 100 0.15 - 100 0.075 - 100	0.5 - 100 0.01 - 100 0.5 - 100 0.2 - 100

### Security

• Improved the receiver's ability to upload multiple SSL CA certificates.

## Feature comparison table

Tracking	Alloy	NetR9
IRNSS updates	Y	N
GLONASS updates	Y	N
BeiDou Gen III GeoStationary	Y	N
QZSS MSAS QZSS-3	Y	Y
SBAS L1	Y	Y
Convert to RINEX Improvements		
GLONASS format fixes	Y	Y
Improvements		
BINEX Galileo Ephemeris options	Y	Y
RTCM3 MSM 3	Y	Y
BeiDou RTCM	Y	Y
Atmospheric modeling	Y	Y
3rd Party antenna support	Y	Y
RTX Positioning	Y	Y
Security Improvements		
Multiple SSL CA uploading abilities	Y	Y

## **Upgrade procedure**

#### Before upgrading the firmware, please back up and save the receiver's configuration.

For the NetR9 receiver, ensure that the receiver firmware warranty date is 1 November 2018 or later. The Alloy receiver has lifetime firmware upgrades.

To upgrade, use one of the following methods:

- If using the WinFlash utility: Use the latest version that is available with the version 5.48 Web package.
- Receiver Web Interface: Download and install the version 6.08 or 5.48 \*.TIMG file. The firmware files are located on the Trimble Alloy and Trimble NetR9 web pages under the download section. Please see the links below.

Trimble Alloy - <u>www.trimble.com/Real-Time-Networks/Trimble-Alloy.aspx</u>

Trimble NetR9 -

www.trimble.com/support\_trl.aspx?Nav=Collection-69991&pt=NetR9%20Support

## **Legal notices**

Trimble Inc. Engineering & Construction Group 10368 Westmoor Drive 5475 Kellenburger Road Dayton, Ohio 45424-1099 USA 800-538-7800 (toll-free in USA) +1-937-245-5600 Phone +1-937-233-9004 Fax www.trimble.com

#### **Copyright and trademarks**

© 2020, Trimble Inc. All rights reserved.

Trimble, the Globe & Triangle logo, and NetR9 are trademarks of Trimble Inc., registered in the United States and in other countries. Alloy and ProPoint are trademarks of Trimble Inc. Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.

#### **Release notice**

This is the August 2020 release (Revision A) of the Release Notes. It applies to version 5.48/6.08 of the Alloy and NetR9 firmware.

#### **Product warranty information**

For applicable product warranty information, please refer to the Warranty Card included with this Trimble product, or consult your Trimble reseller